

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003207**Date Inspected:** 09-Jul-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China**CWI Name:** C.M. Chen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector Tim McClendon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

This Caltrans QA Inspector has been assigned to the ZPMC, ABF, Caltrans group tagging team performing the review of numerous QC and QA documents for the purpose of continuing with the on-going group tagging of the segments identified below.

South Fabrication Bay OBG Assemblies

OBG Assembly Segment 3AE- Caltrans QA observed this segment is idle on this date. There are no activities to report.

OBG Assembly Segment 3BE- Caltrans QA observed this segment is idle on this date. There are no activities to report.

OBG Assembly Segment 4AE- Caltrans QA observed ZPMC in the process of fitting up of floor beam at SSD 019, panel point 24.

OBG Assembly Segment 4BE- Caltrans QA observed ZPMC in the process of FCAW welding CJP of FL3 to Side Plate E7 B side at SSD18, Panel Point 28. Caltrans QA observed ZPMC in the process of performing ultrasonic

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

examination on Splice D6 to E7. This testing was reported by ZPMC personnel Wang Lu to be for information only.

North Fabrication Bay OBG Assemblies

OBG Assembly Segment 5BW- Caltrans QA observed this segment is idle on this date. There are no activities to report.

OBG Assembly Segment 5AW- Caltrans QA observed this segment is idle on this date. There are no activities to report.

OBG Assembly Segment 4BW- Caltrans QA observed ZPMC in the process of FCAW welding CJP of FL3 to Side Plate E7 B side at SSD12, Panel Point 28.

OBG Assembly Segment 4AW- Caltrans QA observed this segment is idle on this date. There are no activities to report.

OBG Assembly Segment 3BW- Caltrans QA observed ZPMC in the process of installing temporary deck panel supports.

OBG Assembly Segment 3AW- Caltrans QA observed ZPMC NDT Technician conduct UT Inspection of CJP weld joining C5 to D6, weld is identified as FL2-1 to FL1-1 after repairs.

Summary of Conversations:

No relevant conversations spoken on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Pat Lowry, (858) 344-2712, who represents the Office of Structural Materials for your project.

Inspected By:	McClendon,Timothy	Quality Assurance Inspector
Reviewed By:	Lanz,Joe	QA Reviewer
